certificate

no. **PS** 18100014 dated 2018-07-20 DGUV Test
Prüf- und Zertifizierungsstelle
Fachbereich Persönliche Schutzausrüstungen

European notified body Identification number 0299

Translation In any case the German original shall prevail

This certificate replaces certificate no. 05100007

GS Certificate

Name and address of the holder of the certificate:

(customer)

Manfred Huck GmbH Netz- und Seilfabrik Aßlarer Weg 13 - 15 35614 Aßlar-Berghausen

Germany

Product designation:

Safety Net System S

Type:

1903D;1803-100

Testing based on:

EN 1263-1:2014-12 (D) EN 1263-2:2014-12 (D) AfPS GS 2014:01 PAK

Test report:

18 1 0006

Further details:

Prod.-Id. 97 1 0219/huckg/1903100d

net class: A2, nominal mesh width: 100 mm

mesh configuration: diamond (D)

net yarn made of Polypropylene, warp knitted (by a raschel machine),

green

nominal size of the mesh rope: 5,0 mm

border rope made of Polysteel (Polypropylene), nominal diameter: 12 mm

300

Chbereich

Intended purpose:

Safety net for arresting a person's fall from a height.

The type tested meets the requirements specified in article 21 para. 1 of the German Product Safety Act. The holder of the certificate is entitled to affix the GS mark shown overleaf to the products complying with the type tested. At that, the holder of the certificate shall observe the conditions specified overleaf.

The present certificate including the right to affix the GS is valid until: 2023-07-19

Further provisions concerning the validity, the extension of the validity and other conditions are laid down in the Rules of Procedure for Testing and Certification.



Signature Dipl.-Ing Glaser



Postal address: Phone:/Fax: Internet:

Zwengenberger Str. 68 / 42781 Haan +49 (0) 21 29 / 576-431 / +49 (0)800668668838090 E-Mail: psa-zs@bgbau.de www.zs-bgbau.de



GS mark





Standard design

Approved design for a height of 20 mm or less

- The holder of the certificate shall comply with the conditions to be observed in the production of the product specified overleaf in order to ensure conformity with the tested type.
- 2. The Testing and Certification body shall, in regular intervals, carry out control measures for monitoring the production and the correct application of the GS mark.
- 3. The person responsible for the production has been obliged to observe the conditions according to 1. and to accept the control measures.
- 4. The Testing and Certification Body shall withdraw the allocation of the GS mark from the holder of the certificate if the requirements according to article 21 para. 1 of the German Product Safety Act are modified or the conditions according to 1. are not met.
- The GS mark shall only be applied and it shall only be used in advertising, if the conditions according to article 22 para. 1 of the German Product Safety Act are met.